

VEHICLE INSPECTION REPORT

LN67WXF

Ford Transit 350 2.0 TDCi 130ps H2 Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 30/09/2017

Year 2017

Mileage 173,416 Miles
Warranted

Fuel Type Diesel

Colour GREEN

VIN WF0XXXTTGXHB74073

Body Style Panel Van L3

MOT Due 08/10/2025

CAP Clean £2,900.00

CAP Average £2,475.00

CAP Below £1,875.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, TOW BAR, DEADLOCKS (NO KEYS), POWER INVERTOR WITH 240V SOCKETS

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Roof
Chipped
Multiple Chips




3: Door Moulding nsf
Scuffed (Unpainted)
UpTo 100mm



4: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel nsr
Chipped
Multiple Chips



6: Qtr Panel nsr
Dented
Over 30mm



7: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



8: Bumper Rear Moulding
Broken
Replace



9: C Post ns
Dented
With Paint Damage



10: Door nsr
Dented
With Paint Damage



11: Door osr
Dented
With Paint Damage



12: Qtr Panel osr
Dented
With Paint Damage




13: Qtr Panel osr
Dented
Over 30mm



14: Door osf
Scratched
Over 25mm Thru Paint



15: Seat Base Cover osf
Soiled
Heavy



16: Seat Base Cover nsf
Soiled
Heavy



17: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		