

VEHICLE INSPECTION REPORT

C354893

DON BUR BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	VIN	SEPBV38GKDL061428	Steering Combi	Front Lift
Year	2013	Body Style	Trailer	Rear Suspension	Air
Mileage	Not Showing	MOT Due	31/03/2026	Rear Doors	Roller
Fuel Type		Brakes	Drum		
Colour	RED	Axle Combi	Tri		

CORROSION, CRACKED CHASSIS, BPW AXLES, RAISE AND LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF
NSR
OSF
OSR
Spare