

# VEHICLE INSPECTION REPORT

**FN17BRF**

## DAF LF 260

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date	26/07/2017	VIN	XLRAEL3700L463393	Cab Type	DAY CAB
Year	2017	Body Style	Crew Van XLWB	Gearbox	AUTOMATIC
Mileage	354,026 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Air
Colour	WHITE	MOT Due	30/11/2025	Rear Doors	Barn

\*MOT HISTORY INCORRECTLY RECORDED IN MILES/KM\* MOFFAT FORKLIFT BRACKET

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Cruise control
- Front electric windows
- Park assist camera
- Drivers airbag
- Digital radio
- Central locking

## Photos












## Condition Check



## Damage Photos



1: Screen Front  
Chipped  
Over 10mm



2: Bonnet  
Chipped  
Multiple Chips



3: Wing nsf  
Scratched  
Over 25mm Thru Paint



4: Door osf  
Scratched  
Over 25mm Thru Paint



5: Panel Front  
Scratched  
Over 25mm Thru Paint



6: Door Pad osf  
Soiled  
Heavy



7: Seat Base Cover osf  
Torn  
Over 3mm

## Interior



<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	Poor
<b>Seat Condition</b>	Poor	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		