

VEHICLE INSPECTION REPORT

C338109

DON BUR CURTAINSIDE TRI AXLE

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Reg. date	01/01/2013	Colour	GREY	Brakes	Drum
Year	2013	VIN	SEPPM39CDL060519	Rear Suspension	Air
Mileage	TBC	Body Style	Curtainside	Rear Doors	Barn
Fuel Type		MOT Due	31/08/2026		

Tyres

NSF
NSR
OSF
OSR
Spare