

# VEHICLE INSPECTION REPORT

**A162018**

## Volvo B9R PLAXTON PANTHER

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

### Details

Reg. date	10/06/2013	Colour	WHITE	Cab Type	DAY CAB
Year	2013	VIN		Gearbox	AUTOMATIC
Mileage	292,528 Km Warranted	Body Style	Coach	Axle Combi	4x2
Fuel Type		MOT Due	05/09/2026	Rear Suspension	Air

\*5% BUYERS FEE MOD654 FORM TO FOLLOW\* 55 SEATS, FOOT REST AND RECLINING SEATS, OVERHEAD STOWAGE, PA SYSTEM, FULL WIDTH UNDERBODY STORAGE, KNEEL FUNCTION

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Radio/CD
- Air conditioning
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Door Mirror Assy osf  
Broken  
Replace





3: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



4: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



5: Panel Rear  
Scratched  
Over 25mm Thru Paint



6: Panel Rear  
Cracked  
Replace



7: Qtr Panel osr  
Dented  
With Paint Damage

## Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		