

VEHICLE INSPECTION REPORT

C355317

DON BUR BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	Colour	RED	Axle Combi	Tri
Year	2013	VIN	SEPBV38GKDL961816	Steering Combi	Front Lift
Mileage	Not Showing	MOT Due	31/07/2026	Rear Suspension	Air
Fuel Type		Brakes	Disc	Rear Doors	Roller

CORROSION BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



