

# VEHICLE INSPECTION REPORT

**CK22YUR**

## Renault Trafic LL30 BLUE DCI 130PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

### Details

Reg. date	06/06/2022	VIN	VF1FL000168919757	CAP Below	£8,650.00
Year	2022	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	71,418 Miles Not Warranted	MOT Due	20/08/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£10,850.00		
Colour	GREY	CAP Average	£10,050.00		

\*SIDE DOOR HANDLE BROKEN\* AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Dented  
Over 30mm



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: B Post ns  
Scratched  
Over 25mm Thru Paint



4: Door Lock nsf  
Broken  
Replace



5: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



6: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Dented  
With Paint Damage



8: Bumper Rear  
Scratched  
Over 100mm Thru Paint






9: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



10: Door osf  
Scratched  
Over 25mm Thru Paint



11: Door osf  
Scratched  
Over 25mm Thru Paint



12: Dash Warning Lights  
Displayed  
No Action

Interior

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	OK	<b>Odour</b>	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault