

VEHICLE INSPECTION REPORT

WDS255V

SCANIA 111

Imported

Inspection

Vehicle

VAT	Margin
V5	To Follow

Details

Reg. date	03/06/1998	Fuel Type	Diesel	Body Style	TILT
Year	1980	Colour	YELLOW/BLUE	Gearbox	MANUAL
Mileage	TBC	VIN	4213351	Axle Combi	6x2

FULLY REFURBISHED BETWEEN 2000 & 2005, NEW TILT BODY FITTED IN 2006 C/W CARAVAN ACCOMODATION FITTED INTO THE REAR IN 2007. BUILT IN GENERATOR, PRESSURE WASHER & 2,000 LITRES OF WATER STORAGE (2X IBC'S). THE TRUCK HAS COMPLETED MANY ROAD RUNS OVER THE YEARS AROUND THE UK AND EUROPE.

Tyres

NSF
NSR
OSF
OSR
Spare