

VEHICLE INSPECTION REPORT

C401314

MONTRACON MACHINE CARRIER

| Inspection | Vehicle |
|------------|---------|
| | |

| VAT | Plus VAT |
|-----|----------|
| V5 | N/A |

Details

| Reg. date | | Colour | BLACK | Brakes | Drum |
|-----------|------|------------|-------------------|-----------------|------|
| Year | 2015 | VIN | SMRM3ASCXFN114840 | Axle Combi | Tri |
| Mileage | TBC | Body Style | Trailer | Rear Suspension | Air |
| Fuel Type | | MOT Due | Expired | | |

BPW AXLES, REAR LIFT, HYDRAULIC RAMP, WINCH. RAISE AND LOWER VALVE

Tyres

NSF

NSR

OSF

OSR

Spare

Photos















