

# VEHICLE INSPECTION REPORT

**FN17BTO**

## Daf LF 260

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	26/07/2017	VIN	XLRAEL3700L463856	Axle Combi	4x2
Year	2017	Body Style	Curtainside	Rear Suspension	Air
Mileage	410,853 Km Warranted	MOT Due	31/07/2026	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

SURROUND CAMERA SYSTEM, FORK LIFT BRACKETS

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Front parking sensor
- Front electric windows
- Park assist camera
- Drivers airbag

## Photos












## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Panel Front  
Cracked  
Replace



4: Door osf  
Dented  
With Paint Damage



5: Door osf  
Scratched  
Over 25mm Thru Paint



6: Screen Front  
Cracked  
Replace



7: Door Pad osf  
Soiled  
Heavy

## Interior

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	Poor
<b>Seat Condition</b>	OK	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		