

# VEHICLE INSPECTION REPORT

**LM66ZZN**

## MERCEDES-BENZ SPRINTER 314 CDI

### Inspection

### Vehicle

|     |           |
|-----|-----------|
| VAT | Plus VAT  |
| V5  | To Follow |

### Details

|           |                            |            |                   |             |           |
|-----------|----------------------------|------------|-------------------|-------------|-----------|
| Reg. date | 05/12/2016                 | Colour     | WHITE             | CAP Clean   | £4,275.00 |
| Year      | 2016                       | VIN        | WDB9061352N689508 | CAP Average | £3,550.00 |
| Mileage   | 154,276 Miles<br>Warranted | Body Style | Dropside          | CAP Below   | £2,650.00 |
| Fuel Type | Diesel                     | MOT Due    | 04/12/2025        | Gearbox     | MANUAL    |

\*OUTSTANDING RECALL \*\*WARNING LIGHT ON DASH\* AD-BLUE

### Tyres

|       |
|-------|
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |

## Features

- Park assist camera
- Front electric windows
- Central locking