

VEHICLE INSPECTION REPORT

X06319

STIHL BG86C LEAF BLOWER *DOES NOT PULL*

Inspection

Vehicle

VAT	Plus VAT
V5	Not Present

Details

DONCASTER STIHL BG86C, 2016, LEAF BLOWER *DOES NOT PULL*

Reg. date	Mileage	TBC	Colour
Year	Fuel Type	VIN	
2016			

Tyres

NSF

NSR

OSF

OSR

Spare