

VEHICLE INSPECTION REPORT

FJ08LXH

HAYTOR

Inspection		Vehicle			
		VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	11/03/2008	Fuel Type	Diesel	Body Style	RIDE ON MOWER
Year	2008	Colour	GREEN	Gearbox	HYDROSTATIC
Mileage	4,415 Hours Not Warranted	VIN	924E270000136	Axle Combi	4WD
Tyres NSF					
NSR					
OSF					
OSR					
Spare					

Photos















