

VEHICLE INSPECTION REPORT

LS23KAX

Citroen Relay 35 2.2 BLUE HDI 140PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 31/03/2023

Year 2023

Mileage 60,592 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF7YCBPFB12W60646

Body Style Panel Van L2

MOT Due 30/03/2026

CAP Clean £9,800.00

CAP Average £9,250.00

CAP Below £8,125.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing of
Chipped
1 To 5



2: Bonnet
Chipped
Multiple Chips



3: Door Mirror Assy nsf
Broken
Replace



4: Door nsr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



8: Qtr Panel osr
Dented
With Paint Damage



9: Door Mirror Assy osf
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK