

VEHICLE INSPECTION REPORT

PF68YUL

Fiat Ducato 35 2.3 Multijet 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/02/2019

VIN ZFA25000002J32413

CAP Below £3,125.00

Year 2019

Body Style Panel Van MWB

Gearbox MANUAL

Mileage 103,119 Km Warranted

MOT Due 31/01/2026

Gears 6

Fuel Type Diesel

CAP Clean £4,450.00

Colour WHITE

CAP Average £3,925.00

SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF


OSR

Spare

Features

- Bluetooth connection
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Qtr Panel nsr
Dented
Over 30mm



3: Panel Rear
Dented
Over 30mm



4: Panel Rear
Dented
Over 30mm



5: Panel Rear
Dented
Over 30mm



6: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	OK	Odour	Yes
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK