

VEHICLE INSPECTION REPORT

PJ67HKF

Daf CF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	21/11/2017	VIN	XLRTGM4300G181340	Axle Combi	6x2
Year	2017	Body Style	Tractor Unit	Steering Combi	Mid-Lif Steert
Mileage	387,095 Km Warranted	MOT Due	31/05/2025	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	SLEEPER CAB		
Colour	WHITE/GREEN	Gearbox	AUTOMATIC		

SLIDING 5TH WHEEL

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Park assist camera
- Manual sunroof
- Central locking
- Cruise control
- Auxiliary input socket
- Air conditioning
- Cloth seat trim
- Front parking sensor
- Digital radio
- Front electric windows
- Navigation system
- Radio/CD
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Door osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		