

VEHICLE INSPECTION REPORT

DE69MSO

ISUZU N35

Inspection

Vehicle

| | |
|-----|-----------|
| VAT | Plus VAT |
| V5 | To Follow |

Details

| | | | | | |
|-----------|----------------------|------------|-------------------|-----------------|-----------|
| Reg. date | 14/10/2019 | Colour | WHITE | Cab Type | DAY CAB |
| Year | 2019 | VIN | JAANPR75HJ7104123 | Gearbox | AUTOMATIC |
| Mileage | 254,425 Km Warranted | Body Style | Flatbed | Axle Combi | 4x2 |
| Fuel Type | Diesel | MOT Due | 30/11/2025 | Rear Suspension | Steel |

WARNING LIGHTS ON DASH

Tyres

| |
|-------|
| NSF |
| NSR |
| OSF |
| OSR |
| Spare |

Features

- Park assist camera
- Digital radio