

VEHICLE INSPECTION REPORT

DU66LME

Volvo FH

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 14/02/2017

VIN YV2RT40C2HB794845

Axle Combi 6x2

Year 2017

Body Style Tractor Unit

Steering Combi Mid-Lift

Mileage 945,109 Km Not Showing

MOT Due Expired

Rear Suspension Air

Fuel Type Diesel

Cab Type GLOBETROTTER CAB

Colour RED

Gearbox AUTOMATIC

NON-RUNNER, HALF SHAFT REMOVED, NO KEYS, CRACKED WINDSCREEN, MOT MILEAGE HISTORY POSSIBLE IN KM/MILES INCORRECTLY, SLIDING 5TH WHEEL, COFFEE MACHNE & TV IN CAB, CB RADIO, MOT SHOWS 908,958KM 30/05/2024

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features

- Bluetooth connection
- Air conditioning
- Leather seat trim
- Cruise control
- Front electric windows
- Park assist camera
- Drivers airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Screen Front
Cracked
Replace



2: Panel Front
Cracked
Replace



3: Panel Front
Dented
With Paint Damage



4: Panel Front
Dented
With Paint Damage



5: Bonnet
Dented
Over 30mm



6: Badgedecal Front
Missing
Replace



7: Badgedecal Front
Missing
Replace



8: Bonnet
Dented
With Paint Damage



9: Panel Front
Scratched
Over 25mm Thru Paint



10: Panel Front
Cracked
Replace



11: Panel Front
Cracked
Replace



12: Bumper Front Grill
Broken
Replace



13: Bumper Front Moulding
Missing
Replace



14: Bumper Front
Cracked
Over 25mm



15: Bumper Front Moulding
Missing
Replace



16: Flasher Side Repeater ns
Missing
Replace



17: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint



18: Qtr Panel Moulding ns
Missing
Replace



19: Qtr Panel Moulding ns
Missing
Replace



20: Lamp osr
Missing
Replace



21: Unclassified
Major Parts Missing
Report Only



22: Qtr Panel Moulding os
Scratched (Painted)
Over 25mm Thru Paint



23: Door Moulding osf
Missing
Replace



24: Door Pad osf
Broken
Replace

Interior

Carpet Condition	OK
Seat Condition	OK

Upholstery Condition	Poor
Odour	-