

VEHICLE INSPECTION REPORT

Vehicle

K154TBB

VOLVO FL10

Inspection

Buyer To Apply BLUE	Gearbox	MANUAL	
RILIE	Goorbox	MANULAL	
DITIE	Coarbox	MANULAL	
DLUL	Gearbox	MANUAL	
SCVF5A6A8PC905229	Axle Combi	4x2	
Tractor Unit			
SLEEPER CAB			
	Tractor Unit		Tractor Unit

ORIGINAL CONDITION, ORIGINALLY A GEARTRONIC AND THE PARTS ARE SOLD WITH THE VEHICLE BUT IT HAS BEEN SWAPPED OT A MANUAL GEARBOX. TIPPING GEAR. BEEN USED AS A YARD SHUNTER PRIOR TO THE SALE.

Tyres			
Tyres NSF			
NSR			
OSF			
OSR			
Spare			