

VEHICLE INSPECTION REPORT

A161609

Volvo PLAXTON PANTHER B9R

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	13/05/2013	Colour	WHITE	Cab Type	DAY CAB
Year	2013	VIN	YV3S5P726DA161609	Gearbox	AUTOMATIC
Mileage	236,095 Km Warranted	Body Style	Coach	Axle Combi	4x2
Fuel Type	DIESEL	MOT Due	27/10/2025	Rear Suspension	Air

*5% BUYERS FEE, * -**NOT FOR AUCTION - FOR TENDER ON WED 5TH NOVEMBER**- 53 SEATS + DRIVER, FABRIC RECLINING SEATS WITH FOOT RESTS, 3PT SEAT BELTS, KNEEL FUNCTION, OVER HEAD STOWAGE, EMERGENCY DOOR AT REAR ON O/S, FULL WIDTH STORAGE BELOW, PA SYSTEM, MOD654 FORM IN OFFICE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Radio/CD
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Seat Base Cover osf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated

OK

DPF light illuminated

OK

ABS light illuminated

OK