

VEHICLE INSPECTION REPORT

BV57PGO

Ford Transit T350 2.4 TDCI 115PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 17/11/2007

Year 2007

Mileage 218,542 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXBDFX7S25318

Body Style Access Platform

Service history Yes

Service documents Electronic / Online

MOT Due Expired

Cab Type DAY CAB

Gearbox MANUAL

Gears 6

Axle Combi 4x2

Rear Suspension Steel

VERSALIFT EUROTREL 36NF LIFT (YEAR 2007)

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bonnet
Chipped
Multiple Chips



3: Qtr Panel nsr
Dented
Over 30mm



4: Door osr
Dented
With Paint Damage



5: Screen Front
Chipped
Over 10mm



6: Door Pad osf
Soiled
Heavy



7: Carpets Front
Holed
Over 3mm



8: Fascia Panel
Holed
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Poor OK	Odour	Poor No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		