

VEHICLE INSPECTION REPORT

PO13DWU

DAF LF 45.140

Inspection

Vehicle

| | |
|-----|-----------|
| VAT | Plus VAT |
| V5 | To Follow |

Details

| | | | | | |
|-----------|---------------------------|------------|-------------------|-----------------|------------|
| Reg. date | 20/03/2013 | VIN | XLRAE45FF0L424887 | Axle Combi | 4x2 |
| Year | 2013 | Body Style | Box Van | Rear Suspension | Steel |
| Mileage | 1,058,415 Km Warranted | MOT Due | 31/03/2026 | Tail Lift | Cantilever |
| Fuel Type | Diesel | Cab Type | DAY CAB | | |
| Colour | RED | Gearbox | MANUAL | | |

COLLECTED AS NON RUNNER, CORROSION, CLUTCH/STARTER MOTOR ISSSUE

Tyres

| |
|-------|
| NSF |
| NSR |
| OSF |
| OSR |
| Spare |

Features

- Digital radio

Photos





