

VEHICLE INSPECTION REPORT

PF69HWV

Daf XF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	21/01/2020	Colour	WHITE	Gearbox	AUTOMATIC
Year	2020	VIN	XLRTGH4300G287247	Axle Combi	6x2
Mileage	412,705 Km Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift Steer
Fuel Type	Diesel	Cab Type	SPACE CAB	Rear Suspension	Air

NON-RUNNER - WILL NOT TURN OVER, WARNING LIGHTS ON DASH SLIDING 5TH WHEEL

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Cloth seat trim
- Digital radio


Photos







Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	Fault		