

VEHICLE INSPECTION REPORT

PJ69XKV

DAF XF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	22/01/2020	Colour	WHITE	Gearbox	AUTOMATIC
Year	2020	VIN	XLRTGH4300G286680	Axle Combi	6x2
Mileage	443,279 Km Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift Steer
Fuel Type	Diesel	Cab Type	SLEEPER CAB	Rear Suspension	Air

NON-RUNNER - WILL NOT TURN OVER, HALF SHAFT REMOVED SLIDING 5TH WHEEL

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Number Plate Front
Missing
Replace



2: Bumper Front
Rusted
Over 5mm



3: Panel Rear
Dented
Over 30mm



4: Other
N/A
N/A

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition Poor
Odour -