

VEHICLE INSPECTION REPORT

BT68LVO

IVECO EUROCARGO 120-210

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	09/01/2019	VIN	ZCFAG1EF602687274	Cab Type	DAY CAB
Year	2019	Body Style	Curtainside	Gearbox	AUTOMATIC
Mileage	288,924 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Electronic / Online	Rear Suspension	Air
Colour	WHITE	MOT Due	31/01/2026	Tail Lift	Cantilever

WEIGH SYSTEM, SURROUND CAMERA SYSTEM

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Digital radio
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door Mirror Assy nsf
Broken
Replace



3: Bumper Front Moulding
Broken
Replace



4: Door osf
Scratched
Over 25mm Thru Paint



5: Door osf
Scratched
Over 25mm Thru Paint



6: Door Pad osf
Broken
Replace



7: Carpets Front
Holed
Over 3mm



8: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		