

VEHICLE INSPECTION REPORT

FN17BTF

Daf LF 260

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 05/07/2017

VIN XLRAEL3700L463769

Axle Combi 4x2

Year 2017

Body Style Curtainside

Rear Suspension Air

Mileage 396,953 Km Warranted

MOT Due 31/07/2026

Rear Doors Barn

Fuel Type Diesel

Cab Type DAY CAB

Colour WHITE

Gearbox AUTOMATIC

MOT MILEAGE HISTORY INCORRECTLY RECORDED IN MILES/KM SURROUND CAMERA SYSTEM, FORKLIFT BRACKET

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4


Features

- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Front parking sensor
- Front electric windows
- Park assist camera
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



6: Door osf
Scratched
Over 25mm Thru Paint



7: Qtr Panel Trim os
Scuffed
Over 25mm



8: Door Pad osf
Soiled
Heavy



9: Seat Base Cover osf
Torn
Over 3mm

10: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		