

VEHICLE INSPECTION REPORT

DX67KRU

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	24/10/2017	Colour	WHITE	Cab Type	DAY CAB
Year	2017	VIN	XLRAEL1500L467017	Gearbox	MANUAL
Mileage	176,499 Km Warranted	Body Style	Dropside	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	31/10/2025	Rear Suspension	Steel

PENNY HYDRAULICS ML500 SWING LIFT, WEIGH SYSTEM.

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Qtr Panel osr
Dented
With Paint Damage



4: Tailgate
Rusted
Over 5mm



5: Qtr Panel nsr
Dented
With Paint Damage



6: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK