

VEHICLE INSPECTION REPORT

BT68LVV

Iveco Eurocargo 120-210

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 03/01/2019

Year 2019

Mileage 408,759 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFAG1EFX02687410

Body Style Curtainside

Service history Yes

Service documents Electronic / Online

MOT Due 31/01/2026

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Air

Tail Lift Cantilever

WARNING LIGHT ON DASH

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features


- Park assist camera
- Radio/CD

Photos





Condition Check



Damage Photos



1: Door osf
Scratched
Over 25mm Thru Paint



2: Door osf
Chipped
Multiple Chips



3: A Post os
Chipped
Multiple Chips



4: Front TowEye Cvr
Missing
Replace



5: Door nsf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault		