

VEHICLE INSPECTION REPORT

SJ67LFK

Iveco Daily 35 -140 2.3

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 03/10/2017

Year 2017

Mileage 47,260 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFCD35A505175649

Body Style Dropside LWB

MOT Due 02/10/2026

CAP Clean £8,700.00

CAP Average £7,400.00

CAP Below £5,600.00

Gearbox MANUAL

Gears 6

Tail Lift Column

WB 3750, TOW BAR, WINCH

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Carpets Front
Torn
Over 10mm



2: Seat Base Cover osf
Torn
Over 3mm



3: Bonnet
Chipped
Multiple Chips



4: Door osf
Dented
With Paint Damage



5: Qtr Panel osr
Dented
With Paint Damage



6: Qtr Panel nsr
Dented
Over 30mm



7: Door nsr
Dented
Over 30mm

Interior

Carpet Condition	Poor	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK