

# VEHICLE INSPECTION REPORT

**SJ66WYU**

## Iveco DAILY 50-180

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 30/09/2016

Year 2016

Mileage 74,930 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFC150D705112171

Body Style Dropside Double Cab

MOT Due 30/09/2026

CAP Clean £5,700.00

CAP Average £4,750.00

CAP Below £3,500.00

Gearbox AUTOMATIC

Tail Lift Column

WB 3450

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Park assist camera
- Radio/CD
- Front electric windows
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Wing osf  
Dented  
With Paint Damage





3: Door osf  
Dented  
With Paint Damage



4: Qtr Panel osr  
Dented  
With Paint Damage



5: Tailgate  
Dented  
Over 30mm



6: Qtr Panel nsr  
Dented  
With Paint Damage

**Interior**

<b>Carpet Condition</b>	-	<b>Upholstery Condition</b>	-
<b>Seat Condition</b>	-	<b>Odour</b>	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK