

## VEHICLE INSPECTION REPORT

**YG20TTY**

### Ford Ranger 2.0 ECOBLUE XL 170PS

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 To Follow

#### Details

Reg. date 18/06/2020

Year 2020

Mileage 74,096 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN 6FPGXXMJ2GKY15566

Body Style Pickup Double Cab

MOT Due 11/03/2026

CAP Clean £9,375.00

CAP Average £8,375.00

CAP Below £6,875.00

Gearbox MANUAL

Gears 6

Axle Combi 4x4

\*ACCIDENT DAMAGE - MAY OR MAY NOT APPEAR ON VCAR\* AD-BLUE, TOW BAR, ROOF RACK, E/ MIRRORS, HEATED WINDSCREEN, MICROWAVE, WATER BOILER, AUXILIARY FUSES

#### Tyres

NSF

NSR

OSF

OSR

Spare

### Features

- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking

### Photos










## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front Grill  
Missing  
Replace



3: Bumper Front  
Cracked  
Over 25mm



4: Bumper Front Moulding  
Broken  
Replace



5: Wing nsf  
Dented  
With Paint Damage



6: Unclassified  
Substantial Accident Damage  
Report Only



7: Seat Base Cover osf  
Soiled  
Heavy



8: Seat Base Cover nsf  
Soiled  
Heavy



9: Fascia Panel  
Missing  
Replace

## Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK	Poor	Poor	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault