

# VEHICLE INSPECTION REPORT

**WV21RXZ**

## FORD TRANSIT 350 2.0 ECOBLUE 130PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 07/04/2021

Year 2021

Mileage 53,625 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0CXXTTRCLL48327

Body Style Tipper Double Cab

MOT Due 06/01/2026

CAP Clean £14,050.00

CAP Average £12,800.00

CAP Below £10,750.00

Gearbox MANUAL

Gears 6

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Front electric windows

## Photos










## Condition Check



## Damage Photos



1: Wing osf  
Dented  
Between 10mm + 30mm



2: Bumper Front  
Cracked  
Over 25mm



3: Front TowEye Cvr  
Missing  
Replace



4: Fog Lamp Surround ns  
Scratched (Painted)  
Over 25mm Thru Paint



5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



6: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



7: Door Moulding nsr  
Scuffed (Unpainted)  
UpTo 100mm



8: Door Moulding nsf  
Scuffed (Unpainted)  
UpTo 100mm



9: Door nsr  
Scratched  
UpTo 25mm Not Thru Paint



10: Door Moulding osr  
Scuffed (Unpainted)  
UpTo 100mm



11: Door osr  
Scratched  
Over 25mm Not Thru Paint



12: Door osr  
Scratched  
UpTo 25mm Not Thru Paint



13: Door osf  
Chipped  
Edge Chip



14: Door Moulding osf  
Scuffed (Unpainted)  
UpTo 100mm





15: Door Mirror Assy osf  
Scuffed (Unpainted)  
UpTo 100mm

16: Seat Base Cover osf  
Holed  
Over 3mm

## Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	