

VEHICLE INSPECTION REPORT

SP13WHF

Ford Ranger 2.2 TDCi 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 26/04/2013

Year 2013

Mileage 75,649 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN 6FPPXXMJ2PDJ86539

Body Style Pickup Double Cab

MOT Due 24/03/2026

CAP Clean £4,050.00

CAP Average £3,200.00

CAP Below £2,175.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH TOW BAR

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Burn
Over 3mm



2: Sill os
Rusted
Over 5mm



3: Bonnet
Dented
Over 2 UpTo 10mm



4: Door osf
Dented
With Paint Damage



5: Tailgate
Dented
With Paint Damage



6: Qtr Panel nsr
Dented
With Paint Damage



7: Door nsf
Chipped
Edge Chip

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK