

# VEHICLE INSPECTION REPORT

**C385521**

## KING MACHINE CARRIER

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | N/A      |

### Details

|           |             |            |                   |                 |      |
|-----------|-------------|------------|-------------------|-----------------|------|
| Reg. date | 01/01/2014  | Colour     | BLACK             | Brakes          | Drum |
| Year      | 2014        | VIN        | SKMGTSZ44EKT11811 | Axle Combi      | Tri  |
| Mileage   | Not Showing | Body Style | Trailer           | Rear Suspension | Air  |
| Fuel Type |             | MOT Due    | 30/11/2025        |                 |      |

GIGGANT AXLES, FLIPTOE RAMP, OUT RIGGERS, RAISE & LOWER VALVE, FERRY LASHING RINGS

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos



