

VEHICLE INSPECTION REPORT

50032

KUBOTA AM3300

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/1999	Fuel Type	Diesel	Body Style	Ride on Mower
Year	1999	Colour		Gearbox	Automatic
Mileage	402 Hours Not Warranted	VIN		Axle Combi	4x2

COLLECTOR BOX

Tyres

NSF
NSR
OSF
OSR
Spare

Photos





