

# VEHICLE INSPECTION REPORT

**GN19HFC**

## Mercedes-Benz Econic 2630

**Non Runner**

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date	01/04/2019	Colour	WHITE	Gearbox	AUTOMATIC
Year	2019	VIN	WDB9560332V255527	Axle Combi	6x2
Mileage	Not Showing	Body Style	Refuse Collector	Rear Suspension	Steel
Fuel Type	Diesel	Cab Type	CREW CAB		

\*NON RUNNER, DOES NOT POWER UP/ MAY OR MAY NOT APPEAR ON VCAR\* MOT SHOWS 76,939 KM 11/04/2024, APPROX HALF A TONNE OF WASTE IN THE REAR, DENNIS EAGLE BODY, SPLIT TERBERG LIFT

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


### Photos







Condition Check



Damage Photos



1: Other  
N/A  
N/A



2: Other  
N/A  
N/A





3: Fog Lamp Surround os  
Broken  
Replace



4: Other  
N/A  
N/A



5: Bonnet  
Missing  
Replace



6: Other  
N/A  
N/A



7: Screen Front  
Cracked  
Replace



8: Other  
N/A  
N/A





9: Other  
N/A  
N/A



10: Headlamps  
Broken  
Replace



11: Other  
N/A  
N/A



12: Other  
N/A  
N/A



13: Other  
N/A  
N/A



14: Other  
N/A  
N/A



15: Other  
N/A  
N/A

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs		Fault	