

VEHICLE INSPECTION REPORT

SSX108V

SCANIA 111

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Reg. date	04/01/1980	Colour	BLUE/RED	Gearbox	MANUAL
Year	1980	VIN	1030816	Axle Combi	4x2
Mileage	328,011 Km Not Warranted	Body Style	Tractor Unit		
Fuel Type	Diesel	Cab Type	DAY CAB		

BRAKES WOUND OFF, CLUTCH PACK NOT FUNCTIONING PROPERLY, WINCH NEEDED

Tyres

NSF
NSR
OSF
OSR
Spare

Photos





