

VEHICLE INSPECTION REPORT

N586YRM

SCANIA R113.360 TOPLINE STREAMLINE

Inspection Vehicle

| VAT | Plus VAT |
|-----|-----------|
| V5 | To Follow |

Details

| Reg. date | 01/01/1996 | Fuel Type | Diesel | Body Style | Tractor Unit | |
|-----------|----------------|-----------|----------|------------|--------------|--|
| Year | 1996 | Colour | WHITE | Gearbox | MANUAL | |
| Mileage | 612,883 Km Not | VIN | 04352542 | Axle Combi | 4x2 | |
| | Warranted | • | | | | |

PART BUILT BEAVERTAIL BODY

Tyres

NSF

NSR

OSF OSR

Spare

Photos















