

VEHICLE INSPECTION REPORT

PE17HSK

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 14/03/2017

Year 2017

Mileage 1,061,931 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G150640

Body Style Tractor Unit

MOT Due 31/10/2025

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

COLLECTED AS NON RUNNER, OIL MODULE, SHOCK ABSORBERS, BRAKE CYLINDER ISSUES

Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4

Features

- Air conditioning


Photos









Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips



2: Other
N/A
N/A

No Image

3: Bonnet
Chipped
Multiple Chips

No Image

4: Screen Front
Chipped
Over 10mm

No Image

5: Wing nsf
Chipped
Multiple Chips

No Image

6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm

No Image

7: Other
N/A
N/A

No Image

8: Other
N/A
N/A

No Image

No Image

9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

10: Other
N/A
N/A

No Image

11: Other
N/A
N/A

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK