

VEHICLE INSPECTION REPORT

PG66UET

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 22/02/2017

Year 2017

Mileage 1,264,698 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G147928

Body Style Tractor Unit

Service history Yes

Service documents Printout

MOT Due 31/05/2026

Cab Type NORMAL SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

COLLECTED AS NON - RUNNER

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4



OSO1 OSO2 OSO3 OSO4

Features


- Cruise control
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Dented
With Paint Damage



4: Panel Front
Poor Previous Repair
Poor Colour



5: Door Mirror Assy nsf
Broken
Replace



6: Door nsf
Dented
With Paint Damage



7: Wing nsf
Scratched
Over 25mm Thru Paint



8: Qtr Panel Moulding ns
Missing
Replace



9: Qtr Panel Moulding os
Missing
Replace



10: Door osf
Scratched
Over 25mm Not Thru Paint



11: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		-
Engine Runs	OK		No Excessive Smoking	OK	
EML light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK				