

# VEHICLE INSPECTION REPORT

**MA56293**

## KRONE CURTAINSIDE EUROLINER

### Inspection

### Vehicle

VAT	Plus VAT
V5	N/A

### Details

Reg. date	01/01/2015	Colour	BLUE	Axle Combi	Tri
Year	2015	VIN	WKESD000000	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Drum		

\*NOT REGISTERED IN THE UK\* BPW AXLES, RAISE AND LOWER VALVE, FERRY LASHING RINGS, ENXL RATED BODY

### Tyres

NSF
NSR
OSF
OSR
Spare