

VEHICLE INSPECTION REPORT

KS66XVF

VOLVO FE 280

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	03/01/2017	Colour	MAUVE/PURPLE	Gearbox	AUTOMATIC
Year	2017	VIN	YV2V0Y1C7HZ110621	Axle Combi	6x2
Mileage	514,115 Km Not Warranted	Body Style	Curtainside	Rear Suspension	Air
Fuel Type	Diesel	MOT Due	31/03/2026	Rear Doors	Barn

REAR LIFT

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Park assist camera
- Digital radio
- Air conditioning