

# VEHICLE INSPECTION REPORT

**M677SUY**

## SCANIA R143.450 TOPLINE STREAMLINE

### Inspection

### Vehicle

VAT	Margin
V5	To Follow

### Details

Reg. date	24/09/1994	Colour	WHITE	Axle Combi	4x2
Year	1994	VIN	01138489	Rear Suspension	Steel
Mileage	860,175 Km Not Warranted	Body Style	Tractor Unit		
Fuel Type	Diesel	Gearbox	MANUAL		

BELIEVED TO HAVE BEEN SAT IN A SCANIA SHOWROOM FOR AROUND 2-3 YEARS WHEN NEW, SPEC'D WITH STEEL SUS. TO PREVENT IT FROM SAGGING, TWIN BUNK

### Tyres

NSF
NSR
OSF
OSR
Spare

## Features

- Air conditioning

## Photos









