

# VEHICLE INSPECTION REPORT

**PK68YYO**

## Daf XF 480

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 10/01/2019

VIN XLRTSH4300G229546

Doors 2

Year 2019

Body Style Tractor Unit

Axle Combi 6x2

Mileage 404,675 Km Warranted

Keys 2

Rear Suspension Air

Fuel Type Diesel

Cab Type SPACE CAB

Colour WHITE

Gearbox Automatic

Rear Lift, Sliding 5th Wheel\* WARNING LIGHT ON DASH\*

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Cruise control
- Air conditioning
- Cloth seat trim

## Photos








Agency		Plate		VTG 6A	007
Reg./Ident. Mark	Vehicle Identification No.		Variant		
PK68YYO	XLRTSH4300G229546				
Type Approval No.					
Manufacturer/Model		DAF /XF 480 FTR			
Function (See note 3)	ARTIC R	Year of Original Registration	10/01/19	Year of Manufacture	2018
(1) Description of Weights Applicable to vehicle	(2) Weights not to be exceeded in GB Britain (See note 5)	(3) EEC Maximum permitted weights (See note 6)	(4) Design weight (See note 7)	Length	Mass
Gross Weight (See note 8)	26000	26000	27000	6710	2550
Train Weight (See note 9)	44000	40000	50000	a. Coupling device in use (See note 11)	4500
Max. Train Weight (See note 10)	44000	44000		b. Coupling device in use (See note 11) as reported next to (a)	4500
Axis Weights (See note 12)				Date of issue	
Axis 1	8000	8000		DEPARTMENT FOR TRANSPORT GREAT BRITAIN	
Axis 2	11500	11500			
Axis 3	7500	7500			
Axis 4					
REPLACEMENT					
Printed on 05/02/19					

DAF TRUCKS N.V.		ADR4
GB	kg	kg
1 - 25000	kg	kg
2 - 44000	kg	kg
3 - 3000	kg	kg
4 - 11500	kg	kg
T - 7500	kg	kg
T - 19000	kg	kg
1 - 2500	kg	kg
2 - 4400	kg	kg
3 - 3000	kg	kg
4 - 11500	kg	kg
T - 7500	kg	kg
T - 19000	kg	kg
Type		Motor no.
E4		1349749



## Condition Check



## Damage Photos



1: Door Moulding of  
Scuffed (Unpainted)  
Over 100mm



2: Bumper Front Moulding  
Scratched (Painted)  
Over 25mm Thru Paint



3: Wing osf  
Scratched  
UpTo 25mm Thru Paint

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
EML light illuminated		Fault	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK