

VEHICLE INSPECTION REPORT

PE17HUH

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 20/03/2017

Year 2017

Mileage 1,103,177 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G151662

Body Style Tractor Unit

Service history Yes

Service documents Printout

MOT Due 28/02/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

COLLECTED AS NON-RUNNER, CALIPER AND CAB TILT LIFT PUMP REQ.ATTN

Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features


- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Dented
With Paint Damage



4: Door nsf
Dented
With Paint Damage



5: Wing nsf
Poor Previous Repair
Rippled UpTo 30%



6: Panel Rear
Dented
With Paint Damage



7: Wing osf
Poor Previous Repair
Rippled UpTo 30%



8: Door osf
Dented
Over 30% Of Panel

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		