

VEHICLE INSPECTION REPORT

940,500 Km Warranted MOT Due

Diesel

BLUE

MD68ZYH

SCANIA S 500

Inspection

		V5	Present	_	
Details					
Reg. date	03/01/2019	VIN	YS2S6X20005532352	Axle Combi	6x2
Year	2019	Body Style	Tractor Unit	Steering Combi	Mid-Lift

Plus VAT

31/01/2026

HIGHLINE CAB

AUTOMATIC

Cab Type

Gearbox

Vehicle VAT

Tyres

Mileage

Colour

Fuel Type

NSF

NSR

OSF

OSR

Spare

Features

• Park assist camera

• Air conditioning

• Leather seat trim

Rear Suspension

Air

Photos













^{*}CRACKED WINDSCREEN* SLIDING 5TH WHEEL, SURROUND CAMERA SYSTEM



