

VEHICLE INSPECTION REPORT

DK55LAA

ERF D 20

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	17/12/2005	Colour	WHITE	Cab Type	DAY CAB
Year	2005	VIN	WMAH06ZZ86G184484	Gearbox	AUTOMATIC
Mileage	366,189 Km Warranted	Body Style	Tractor Unit	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/11/2025	Rear Suspension	Air

INPUT ERROR ON MOT MILEAGE HISTORY DRUM HYDRAPACK, TWIN LINE PTO HYDRAULICS

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Aperture Seal nsf
Broken
Replace



3: Door Mirror Assy nsf
Broken
Replace



4: Door nsf
Chipped
Multiple Chips



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Qtr Panel Moulding ns
Broken
Replace



7: Door osf
Dented
With Paint Damage



8: Door Moulding osf
Broken
Replace



9: Door Pad osf
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		