

VEHICLE INSPECTION REPORT

FN17BTY

Daf LF 260

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 17/07/2017

Year 2017

Mileage 403,362 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAEL3700L463905

Body Style Curtainside

Service history Yes

Service documents Electronic / Online

MOT Due 31/08/2026

Cab Type DAY CAB

Gearbox AUTOMATIC

Rear Suspension Air

Rear Doors Barn

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4


Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Features


- Radio/CD
- Air conditioning

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Grill
Broken
Replace



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



5: Door osf
Dented
Over 30mm



6: Qtr Panel osr
Dented
Over 30mm



7: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK