

VEHICLE INSPECTION REPORT

PK67VEY

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	06/11/2017	VIN	XLRTGM4100G180634	Cab Type	SLEEPER CAB
Year	2017	Body Style	Tractor Unit	Gearbox	AUTOMATIC
Mileage	859,175 Km Warranted	Service history	Yes	Axle Combi	6x2
Fuel Type	Diesel	Service documents	Printout	Steering Combi	Mid-Lift Steer
Colour	RED	MOT Due	31/12/2025	Rear Suspension	Air

COLLECTED AS NON-RUNNER, BPV/EGR ISSUES

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Cruise control
- Digital radio
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Door nsf
Dented
With Paint Damage



4: Door osf
Scratched
Over 25mm Not Thru Paint



5: Screen Front
Chipped
Over 10mm



6: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		