

VEHICLE INSPECTION REPORT

WX66KWV

Isuzu D-Max 2.5 TD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	01/11/2016	VIN	MPATFS86JFT030435	CAP Below	£4,100.00
Year	2016	Body Style	Pickup Single Cab	Gearbox	MANUAL
Mileage	71,549 Miles Warranted	MOT Due	31/10/2025	Gears	6
Fuel Type	Diesel	CAP Clean	£6,675.00	Axle Combi	4x4
Colour	WHITE	CAP Average	£5,575.00		

TWIN SIDE LOAD DOOR, TOW BAR, ROOF RACK, POWER INVERTER, FUSE BOX, 240V SOCKETS

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Chipped
Multiple Chips



4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Door nsf
Chipped
Multiple Chips



6: Qtr Panel nsr
Chipped
Multiple Chips



7: Qtr Panel nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Cracked
Replace



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Qtr Panel osr
Chipped
Multiple Chips



11: Qtr Panel osr
Chipped
Multiple Chips



12: Door osf
Chipped
Multiple Chips



13: Wing osf
Chipped
Multiple Chips



14: Wing osf
Dented
With Paint Damage



15: Bumper Front
Scratched
Over 100mm Thru Paint



16: Seat Base Cover osf
Soiled
Heavy



17: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		